



## Retirement Bulletin

Bulletin Number: R-2006-0235-Global  
Date: 01 January 2007

# Multiprotocol Router 5430 Manufacture Discontinue Notice

## REVISION HISTORY

Date	Revision #	Summary of Changes
01 January 2007	Original bulletin	This is the original publication

Last Time Order Date:	April 30, 2007
Last Ship Date:	May 31, 2007
Manufacture Discontinue (MD) Date:	May 31, 2007
End of Life (EOL) Date:	June 1, 2012
Last Supported Software Release:	<i>BayRS 15.7, 15.6, 15.4</i>
Market Regions Affected:	<i>Global, NA, CALA, EMEA, and Asia Pacific</i>

### Introduction

The Multiprotocol Router 5430 product portfolio is being discontinued by Nortel\*. The last order date is April 30, 2007 with the table below providing a list of discontinued codes. Any Multiprotocol Router 5430 order codes not listed in the table have also been discontinued.

The recommended replacement product for the Multiprotocol Router 5430 is the Secure Router 3120. Please note that the Secure Router products are IP WAN routers and do not support legacy multiprotocol features of the BayRS family, including the Multiprotocol Router 5430. The Secure Router 3120 provides superior price/performance with advanced features in the areas of Routing, WAN, VPN, Security, Quality of Service and Network Management.

Technical support for the Multiprotocol Router 5430 products will continue through the normal Nortel Technical Support Center. This notice will also serve as the final EOL notice for the order codes identified below and no additional notice will be issued.

### Definition

Manufacture Discontinue (MD) – This notice serves as formal communication of Nortel Networks' intent to MD the product(s) noted. No further orders will be accepted as of the Last Time Order Date shown above and no further shipments made after the product has

been discontinued. The MD of these products should not be interpreted as the discontinuance of any Nortel Networks agreements to support the existing field population. Services to the existing product base will continue to be provided until the End of Life (EOL) date shown above.

Product Overview (See Table for Detail)

<b>SYSTEM COMPONENTS</b>	
	<b>Base Units</b>
DU0002001	Chassis
DU0005A01	Power Supply (Universal AC) (No power cord included)
DU0005B01	Power Supply (Universal AC) (Includes European Schuko power cord)
DU0005C01	Power Supply (Universal AC) (Includes power cord used in the UK and Ireland)
DU0005D01	Power Supply (Universal AC) (Includes power cord used in Japan)
DU0005E01	Power Supply (Universal AC) (Includes North American power cord)
DU0005F01	Power Supply (Universal AC) (Includes Australian power cord, also used in New Zealand and the PRC)
DU0005G01	Power Supply (Universal AC) (Includes power cord used in Denmark)
DU0005K01	Power Supply (Universal AC) (Includes power cord used in Italy)
DU0005L01	Power Supply (Universal AC) (Includes power cord used in Switzerland)
DU0005M01	Power Supply (Universal AC) (Includes North American 10A/220 power cord)
	<b>PCI Cards</b>
DU0004001	Expansion card
DU2204001	System Processor
	<b>PMC Modules</b>
DU1304001	ATM T1/E1 PMC
DU1304002	ATM T3/E3 PMC.
DU2104001	Dual Sync PMC includes one dual serial adapter
DU2104003	Quad Serial PMC.
	<b>WAN Adapter Module Options</b>
CV0011044	Gray Serial Adapter Module Field Upgrade / Spare
CV0011045	Gray ISDN BRI S/T Adapter Module Field Upgrade/Spare (without NT1)
CV0011046	Gray ISDN BRI U Adapter Module Field Upgrade/Spare (with NT1)
CV0011048	Gray V.34 Modem Adapter Module (North America only) Field Upgrade/Spare
CV0011050	T1/FT1 DSU/CSU Adapter Module (North America only) Field Upgrade/Spare
CV0011053	Gray E1/FE1 Adapter Module Field Upgrade/Spare (RJ)
CV0011054	Gray E1/FE1 Adapter Module Field Upgrade/Spare (BNC)
	<b>ACCESSORIES</b>
	<b>Accessories</b>
AA0011026	Console Cable for Multiprotocol Routers 2430/5430 Models and VPN Router 1010/1050/1100 Models.

AA0018040	Balun Connector/Cable
DU0011009	Quad Serial PMC Adapter Cable Spare.
DU0011010	Passport 5400 Rack Mount Replacement Kit.
<b>FIELD UPGRADES/SPARE OPTIONS</b>	
	<b>DRAM/FLASH Memory</b>
AA0011021	32M Flash PCMCIA Card Spare - Formatted
DU0011004	32MB DRAM.
DU0011006	128MB DRAM.

### Software Dependencies

Software support on the product will continue per Nortel support policy. BayRS 15.7 will continue to be fully supported for one year after manufacture discontinuation and limited support for four more years after full support ends. BayRS 15.6 and 15.4 will continue to have limited support for five years after manufacture discontinuation.

### Alternative/Replacement Products/Solutions

The recommended replacement product for Multiprotocol Router 5430 is the Secure Router 3120. Please note that the Secure Router products are IP WAN routers and do not support legacy multiprotocol features of the BayRS family, including the Multiprotocol Router 5430. The Secure Router 3120 provides superior price/performance with advanced features in the areas of Routing, WAN, VPN, Security, Quality of Service and Network Management.

### Related Product and Sales & Marketing Bulletins (if applicable)

Not applicable.

### Customer Actions

Customers are advised to consider this notification in conducting last time buys or planning a product replacement with the Nortel Secure Router 3120 family. For more information, please contact your Nortel Networks account representative. Content herein is not intended to supercede existing customer contractual commitments.

\*Nortel, the Nortel logo and the Globemark are trademarks of Nortel.

©2006 Nortel Networks Limited. All rights reserved. Nortel, the Nortel logo, and the Globemark design are trademarks of Nortel Networks Limited. All other trademarks are the property of their respective owners.

The information in this document is subject to change without notice. Nortel reserves the right to make changes, without notice, in equipment design as engineering or manufacturing methods may warrant. The statements, configurations, technical data, and recommendations in this document are believed to be accurate and reliable, but are presented without express or implied warranty. Users must take full responsibility for their applications of any products specified in this document. The information in this document is proprietary to Nortel Networks Limited.

To view the most recent version of this bulletin, please visit Nortel's Partner Information Center on the web at: <http://www.nortel.com/pic>.